

Connections & Set-Up Options for RESCUE EcoTech®




SOLID LINES ARE SHOWN FOR CCWLE ROTATION. FOR CWLE ROTATION, CHANGE THE CONNECTOR ORIENTATION TO DASHED LINE.



Counter Clockwise Rotation



Clockwise Rotation



WIRING CHART					
Suggested lead color at Horsepower shown					
HP Rating	Speed	5552ET	5542ET	5532ET	5522ET
1 HP	COOL	BLACK			
	HEAT	YELLOW			
3/4 HP	COOL	YELLOW	BLACK		
	HEAT	BLUE	YELLOW		
1/2 HP	COOL	BLUE	YELLOW	BLACK	
	HEAT	ORANGE	BLUE	YELLOW	
1/3 HP	COOL		BLUE	YELLOW	BLACK
	HEAT		ORANGE	BLUE	YELLOW
1/4 HP	COOL			BLUE	YELLOW
	HEAT			ORANGE	BLUE
1/5 HP	COOL				BLUE
	HEAT				ORANGE

The **red lead** is only for the constant fan/circulation speed