

	B <sup>®</sup>	B-E <sup>®</sup>	B-L <sup>®</sup> / B-W <sup>®</sup>	F <sup>®</sup>	FAST DRY <sup>®</sup>	M <sup>®</sup> / M-10 <sup>®</sup>	WS-3/8 <sup>®</sup>	TYRE MARQUE <sup>®</sup>	Quik Stik <sup>®</sup>	Quik Stik <sup>®</sup> Mini
<b>PERMANENT</b>										
<b>Metals</b>										
Clean, Dry	⊙		⊙	⊙	⊙	⊙			⊙	⊙
Rough	⊙	⊙	⊙	⊙	⊙	⊙			⊙	⊙
Rusty	⊙	⊙		⊙	⊙				⊙	⊙
Oily	⊙									
Wet	⊙								⊙	⊙
Annealing, Heat Treat						⊙				
Low Corrosion	⊙									
<b>Plastics</b>										
Clean, Dry	⊙		⊙	⊙	⊙	⊙			⊙	⊙
Rough	⊙	⊙	⊙	⊙	⊙	⊙			⊙	⊙
Oily										
Wet	⊙								⊙	⊙
<b>Rubber</b>										
Clean, Dry	⊙			⊙	⊙			⊙	⊙	⊙
Rough	⊙			⊙	⊙			⊙	⊙	⊙
Oily	⊙									
Wet	⊙							⊙	⊙	⊙
<b>Glass, Ceramic</b>										
Clean, Dry	⊙				⊙				⊙	⊙
Rough	⊙	⊙			⊙				⊙	⊙
Wet	⊙								⊙	⊙
<b>Brick, Stone</b>										
Clean, Dry	⊙			⊙	⊙				⊙	⊙
Rough	⊙	⊙		⊙	⊙				⊙	⊙
Wet	⊙	⊙		⊙					⊙	⊙
<b>Before Painted Surface</b>										
Bleed-Through Paint			⊙							
No Bleed-Through										
<b>Painted Surface</b>										
Clean, Dry	⊙			⊙	⊙					
Rough	⊙	⊙		⊙	⊙					
Oily	⊙									
Wet	⊙			⊙					⊙	⊙
<b>REMOVABLE</b>										
<b>Non-porous Surfaces</b>										
Clean, Dry							⊙			

⊙ Preferred Selection   ⊙ Secondary Selection